

Attachment B

Work Order Cost Summary

Page 1 of 4

Date: 1/10/2020 10:56:53

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	COSTS
P127491	85210 10 Ford F350 Super Duty 4x4 5.4L	10/14/2019	01/08/2020	CLO	3.50	Labor Cost: \$315.00 Mtl Cost: \$0.00 CONTRACT: \$0.00 <hr/> TOTAL: \$315.00
<u>Work Requested:</u>						
C-SERVICE ANNUAL/D-SERVICE (SEE OWNERS MANUAL)						
15,000 - INSPECT THE COOLANT CONCENTRATION AND ADDITIVE STRENGTH. ADD ENGINE COOLANT ADDITIVE IF NECESSARY. REPLACE FUEL FILTERS.						
45,000 - REPLACE AIR INLET FOAM FILTER (FA-1909).						
60,000 - CHANGE TRANSFER CASE FLUID. FLUSH AND REFILL ENGINE COOLANT. DO NOT ADD ENGINE COOLANT ADDITIVE.						
90,000 - INSPECT THE ACCESSORY DRIVE BELTS						
100,000 - CHANGE THE REAR AXLE FLUID. CHANGE CRANKCASE VENTILATION FILTER ASSY.						
150,000 - CHANGE TRANSMISSION FLUID AND FILTER. CHANGE FRONT AXLE FLUID. CHANGE TRANSFER CASE FLUID. REPLACE ACCESSORY DRIVE BELTS.						
<p>perform c service visual inspection air filter was replaced previous service, fixed exhaust heat shield rattle with hose clamps, insp all fluids all ok all filters ok, check spark plugs gap on 3 cylinders with in spec check brakes and front suspension components ok mileage 56604 JR</p>						
P127489	85210 10 Ford F350 Super Duty 4x4 5.4L	10/06/2019	01/08/2020	CLO	1.00	Labor Cost: \$90.00 Mtl Cost: \$50.38 CONTRACT: \$0.00 <hr/> TOTAL: \$140.38
<u>Work Requested:</u>						
A-SERVICE 8001040 & 6QTS 7901006 (5W/20)						
perform a service change oil and filters mileage 56604 JR						
C111416	85210 10 Ford F350 Super Duty 4x4 5.4L	11/27/2018	11/28/2018	CLO	8.00	Labor Cost: \$540.00 Mtl Cost: \$258.37 CONTRACT: \$0.00 <hr/> TOTAL: \$798.37
<u>Work Requested:</u>						
Loose outer tie rod ends						
Replaced both tie rod ends and rod, replaced ball joint on end of steering link, centered steering wheel and adjusted toe in MILEAGE: 52767						
P126196	85210 10 Ford F350 Super Duty 4x4 5.4L	11/22/2018	11/27/2018	CLO	2.00	Labor Cost: \$135.00 Mtl Cost: \$46.80 CONTRACT: \$0.00 <hr/> TOTAL: \$181.80
<u>Work Requested:</u>						
A-SERVICE 8001040 & 6QTS 7901006 (5W/20)						
Changed oil and filter, checked air filter, checked fluid levels and lights, aired tires, found bad ball joints - repaired on C111416 MILEAGE: 52767						
C110568	85210 10 Ford F350 Super Duty 4x4 5.4L	06/06/2018	06/08/2018	CLO	4.50	Labor Cost: \$303.75 Mtl Cost: \$247.90 CONTRACT: \$0.00 <hr/> TOTAL: \$551.65
<u>Work Requested:</u>						
Miscellaneous - no power to license plate lamp, drivers side running board loose						
License plate lights were never hooked up when Tommy Gate was installed. Fabricate electrical harness to harness to connect license plate light on Tommy Gate to truck side harness. Repalce badly rusted running board tubes. Mileage at time of service 49,837. -						
P125473	85210 10 Ford F350 Super Duty 4x4 5.4L	05/30/2018	06/06/2018	CLO	1.00	Labor Cost: \$67.50 Mtl Cost: \$67.59 CONTRACT: \$0.00 <hr/> TOTAL: \$135.09
<u>Work Requested:</u>						
A-SERVICE 8001040 & 6QTS 7901006 (5W/20)						
Replace air filter, service and inspection as per PM checklist, replaced engine oil and filter, other work done on work order C110568 MILEAGE: 49837						

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	COSTS
C109730	85210 10 Ford F350 Super Duty 4x4 5.4L	12/21/2017	01/02/2018	CLO	3.50	Labor Cost: \$189.00 Mtl Cost: \$646.07 CONTRACT: \$0.00 TOTAL: \$835.07
<u>Work Requested:</u> Request for tire replacement 4- LT245/75-17E Replaced all 4 tires & valve stems, balanced wheels & reset tire monitor. Lightly fluid filmed doors & rocker panels. MILEAGE: 48491						
C109359	85210 10 Ford F350 Super Duty 4x4 5.4L	09/07/2017	12/15/2017	CLO	2.00	Labor Cost: \$104.00 Mtl Cost: \$0.00 CONTRACT: \$0.00 TOTAL: \$104.00
<u>Work Requested:</u> Miscellaneous Signboard will not operate with handheld Mechanic made no remarks						
P124388	85210 10 Ford F350 Super Duty 4x4 5.4L	08/23/2017	09/07/2017	CLO	1.00	Labor Cost: \$52.00 Mtl Cost: \$36.55 CONTRACT: \$0.00 TOTAL: \$88.55
<u>Work Requested:</u> A-SERVICE 8001040 & 6QTS 7901006 (5W/20) Change oil and filter check over,grease,top off fluids and tire air pressures,clean raidator,clean corrosion off of high amp resistor 46622ml						
C108934	85210 10 Ford F350 Super Duty 4x4 5.4L	05/11/2017	05/15/2017	CLO	5.50	Labor Cost: \$286.00 Mtl Cost: \$366.33 CONTRACT: \$0.00 TOTAL: \$652.33
<u>Work Requested:</u> Brakes as needed REPLACED REAR BRAKES AND REAR ROTORS - MILEAGE AT TIME OF SVC: 44345						
C108673	85210 10 Ford F350 Super Duty 4x4 5.4L	03/01/2017	03/17/2017	CLO	17.50	Labor Cost: \$910.00 Mtl Cost: \$176.69 CONTRACT: \$0.00 TOTAL: \$1,086.69
<u>Work Requested:</u> Drive-train, front differential noise. 85210 Arden Hills 2010 Ford F-350 with 43,952 miles brought in to change out front axle u-joints. Parts are ordered on 3/14/2017. Started to take apart. In shop on hoist. Wheel bearing rusted in place, I did get apart with extra work. Replaced front axle u-joints both sides also installed as part of the job Hub service kit, and steering knuckle seal kit. Greased u-joints and test drove good when done.						
C108672	85210 10 Ford F350 Super Duty 4x4 5.4L	03/01/2017	11/27/2017	CLO	0.00	Labor Cost: \$0.00 Mtl Cost: \$0.00 CONTRACT: \$0.00 TOTAL: \$0.00
<u>Work Requested:</u> Drive-train, driver complaint of noisey drive-train coming from the front differential. Closing this duplicate work order, was done under C108673						
P123330	85210 10 Ford F350 Super Duty 4x4 5.4L	10/17/2016	11/07/2016	CLO	4.00	Labor Cost: \$200.00 Mtl Cost: \$37.91 CONTRACT: \$0.00 TOTAL: \$237.91
<u>Work Requested:</u> A-SERVICE 8001040 & 6QTS 7901006 (5W/20) Changed oil and filter, lic inoperative, tommy lift won't take grease, due to lack of maintanace 42675						

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	COSTS
C108021	85210 10 Ford F350 Super Duty 4x4 5.4L	09/09/2016	09/09/2016	CLO	2.00	Labor Cost: \$100.00 Mtl Cost: \$0.00 CONTRACT: \$0.00 TOTAL: \$100.00
<u>Work Requested:</u>						
Computer and Module - Check engine light is on §						
HAD DTC P2270 - O2 SENSOR STUCK LEAN - B1S2. MONITORED SCAN TOOL DATA AND FOUND NO ISSUES. INSPECTED FOR ANY SIGNS OF VACUUM LEAKS, EXHAUST LEAKS OR WIRING DAMAGE - NO ISSUE FOUND. CLEARED DTC, RAN KOER SELF TEST AND TEST DROVE. CODE DID NOT RETURN OR EXHIBIT ANY SIGNS OF AN ISSUE - RETURNED VEHICLE TO SERVICE - MILEAGE: 42149						
C107794	85210 10 Ford F350 Super Duty 4x4 5.4L	07/06/2016	07/06/2016	CLO	3.00	Labor Cost: \$150.00 Mtl Cost: \$0.00 CONTRACT: \$0.00 TOTAL: \$150.00
<u>Work Requested:</u>						
Complaint that A/C not blowing cold						
CLEANED RADIATOR, CONDENSOR, AND THE COMPLETE ENGINE COMPARTMENT. EVACUATED AND CHARGED A/C SYSTEM, ADDED OIL AND TRACER DYE TO SYSTEM. COOLS TO 38-40 DEG.						
C107516	85210 10 Ford F350 Super Duty 4x4 5.4L	04/25/2016	04/25/2016	CLO	2.00	Labor Cost: \$100.00 Mtl Cost: \$105.92 CONTRACT: \$0.00 TOTAL: \$205.92
<u>Work Requested:</u>						
No start, and had to be jump started						
CHARGED AND TESTED BATTERY, NOT HOLDING CHARGE. R&R BATTERY AND CHECKED CHARGING SYSTEM. OK - MILEAGE: 39584						
P122562	85210 10 Ford F350 Super Duty 4x4 5.4L	04/04/2016	04/06/2016	CLO	1.00	Labor Cost: \$50.00 Mtl Cost: \$46.60 CONTRACT: \$0.00 TOTAL: \$96.60
<u>Work Requested:</u>						
A-SERVICE 8001040						
A service, changed motor oil and filter, performed a multi point inspection 39328						
C107370	85210 10 Ford F350 Super Duty 4x4 5.4L	03/07/2016	03/07/2016	CLO	1.00	Labor Cost: \$50.00 Mtl Cost: \$0.00 CONTRACT: \$0.00 TOTAL: \$50.00
<u>Work Requested:</u>						
Wheels, left rear tire leaks						
REPLACED LEFT REAR VALVE STEM. CHECKED THE AIR PRESSURE IN ALL WHEELS - MILEAGE: 39001						
C106886	85210 10 Ford F350 Super Duty 4x4 5.4L	10/06/2015	10/06/2015	CLO	7.50	Labor Cost: \$360.00 Mtl Cost: \$270.41 CONTRACT: \$0.00 TOTAL: \$630.41
<u>Work Requested:</u>						
Brakes - found bad front brakes on inspection §						
REPLACED FRONT BRAKES - MILEAGE: 37086						
P121948	85210 10 Ford F350 Super Duty 4x4 5.4L	09/16/2015	10/06/2015	CLO	1.00	Labor Cost: \$48.00 Mtl Cost: \$57.84 CONTRACT: \$0.00 TOTAL: \$105.84
<u>Work Requested:</u>						
A-SERVICE 8001040						
DID A SERVICE, ROTATED TIRES, RESET OIL LIFE, PROGRAMMED TPMS SENSORS - MILEAGE: 37086						

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	COSTS	
P121354	85210 10 Ford F350 Super Duty 4x4 5.4L	04/16/2015	04/16/2015	CLO	2.00	Labor Cost:	\$96.00
						Mtl Cost:	\$46.60
<u>Work Requested:</u>						CONTRACT:	\$0.00
A-SERVICE 8001040						TOTAL:	\$142.60
CHANGED OIL & FILTER, CHECKED AIR FILTERS, CHECKED FLUIDS, CHECKED TIRES AND BRAKES AND DID AN UNDER CARRIAGE INSPECTION - TESTED TOMMY GATE AND THE PASSENGER SIDE STICKS UNLESS THERE IS A LOAD ON IT, ALSO GREASED TOMMY GATE AS WELL - MILEAGE: 33355							
P120769	85210 10 Ford F350 Super Duty 4x4 5.4L	09/24/2014	09/24/2014	CLO	3.00	Labor Cost:	\$138.00
						Mtl Cost:	\$29.65
<u>Work Requested:</u>						CONTRACT:	\$0.00
A-SERVICE						TOTAL:	\$167.65
CHANGED OIL, LOOK OVER, REPLACED 3 TIRES/BALANCED - CLEAN RADIATOR - MILEAGE: 30369							
C105768	85210 10 Ford F350 Super Duty 4x4 5.4L	07/22/2014	07/22/2014	CLO	1.00	Labor Cost:	\$46.00
						Mtl Cost:	\$8.00
<u>Work Requested:</u>						CONTRACT:	\$0.00
Mount tire and put on right front-- rotate tires as needed reset tire maint moneter						TOTAL:	\$54.00
REPLACE RT FRONT TIRE AND BALANCE, NEED 3 NEW TIRES - MILEAGE: 29203							

REPORT TOTALS	
ACTUAL HOURS:	77.00
LABOR:	\$4,330.25
MATERIAL:	\$2,499.61
CONTRACT:	\$0.00
GRAND TOTAL:	\$6,829.86

23 Work Order(s) listed.