

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	COSTS
P127238	85203 12 Ford F350 Pick-up 4WD 6.2L	08/12/2019	10/21/2019	CLO	12.50	Labor Cost: \$1,100.00 Mtl Cost: \$902.65 CONTRACT: \$0.00 TOTAL: \$2,002.65
<u>Work Requested:</u>						
C-SERVICE ANNUAL/D-SERVICE (SEE OWNERS MANUAL)						
15,000 - INSPECT THE COOLANT CONCENTRATION AND ADDITIVE STRENGTH. ADD ENGINE COOLANT ADDITIVE IF NECESSARY. REPLACE FUEL FILTERS.						
45,000 - REPLACE AIR INLET FOAM FILTER (FA-1909).						
60,000 - CHANGE TRANSFER CASE FLUID. FLUSH AND REFILL ENGINE COOLANT. DO NOT ADD ENGINE COOLANT ADDITIVE.						
90,000 - INSPECT THE ACCESSORY DRIVE BELTS						
100,000 - CHANGE THE REAR AXLE FLUID. CHANGE CRANKCASE VENTILATION FILTER ASSY.						
150,000 - CHANGE TRANSMISSION FLUID AND FILTER. CHANGE FRONT AXLE FLUID. CHANGE TRANSFER CASE FLUID. REPLACE ACCESSORY DRIVE BELTS.						
Replaced 4 tires Replaced shift motor for four wheel drive Inspected vehicle Removed grill and condensor cleaned radiator and coolers Reassembled and charged a/c Inspected and lube tommy gate m81150 jwb						
P127232	85203 12 Ford F350 Pick-up 4WD 6.2L	08/10/2019	10/21/2019	CLO	0.00	Labor Cost: \$0.00 Mtl Cost: \$96.88 CONTRACT: \$0.00 TOTAL: \$96.88
<u>Work Requested:</u>						
5,000 MILE A-SERVICE 8001040 & 7qts 7901006 (5w/20) Service inspect and advise as to vehicle condition						
Changed oil and filter Replaced air filter Inspected vehicle m81150 jwb						
P126627	85203 12 Ford F350 Pick-up 4WD 6.2L	03/27/2019	03/27/2019	CLO	2.00	Labor Cost: \$176.00 Mtl Cost: \$65.78 CONTRACT: \$0.00 TOTAL: \$241.78
<u>Work Requested:</u>						
5,000 MILE A-SERVICE 8001040 & 7qts 7901006 (5w/20) Service inspect and advise as to vehicle condition						
Change oil and filter, replace engine air cleaner, check over, top off fluids and tire air pressures, reset oil life monitor. MILEAGE: 73787						
C111615	85203 12 Ford F350 Pick-up 4WD 6.2L	01/17/2019	01/23/2019	CLO	7.00	Labor Cost: \$472.50 Mtl Cost: \$628.77 CONTRACT: \$0.00 TOTAL: \$1,101.27
<u>Work Requested:</u>						
Driver complaint of loose steering, wandering.						
Found both right outer tie rods loose-replaced, replaced hub lockouts due to noise, replaced stabilizer, both front shocks, performed rotate. MILEAGE: 71711						
C111464	85203 12 Ford F350 Pick-up 4WD 6.2L	12/04/2018	01/07/2019	CLO	5.00	Labor Cost: \$337.50 Mtl Cost: \$419.41 CONTRACT: \$0.00 TOTAL: \$756.91
<u>Work Requested:</u>						
The operator said when selecting a gear from drive to neutral for example, there's a lot of play in the shifter.						
Replaced steering column gear shift lock out assembly MILEAGE: 71328						

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	COSTS
C111265	85203 12 Ford F350 Pick-up 4WD 6.2L	10/16/2018	10/26/2018	CLO	2.50	Labor Cost: \$168.75 Mtl Cost: \$0.00 CONTRACT: \$0.00 TOTAL: \$168.75
<u>Work Requested:</u> Replace tires - tires are already delivered here. LT245/75R17 NOTE: TIRES CHARGED DIRECTLY TO ARDEN HILLS - 179.99 EA TOTAL 719.96 Replaced tires, balanced wheels, reset tire monitor, cleaned radiator. MILEAGE: 68763						
P126000	85203 12 Ford F350 Pick-up 4WD 6.2L	09/25/2018	10/26/2018	CLO	1.00	Labor Cost: \$67.50 Mtl Cost: \$56.89 CONTRACT: \$0.00 TOTAL: \$124.39
<u>Work Requested:</u> A-SERVICE 8001040 & 7qts 7901006 (5w/20) Service inspect and advise as to vehicle condition Serviced and inspected as per pm checklist, oil changed and filter, greased front u-joints. MILEAGE: 68763						
C110463	85203 12 Ford F350 Pick-up 4WD 6.2L	05/16/2018	05/25/2018	CLO	4.50	Labor Cost: \$303.75 Mtl Cost: \$0.00 CONTRACT: \$0.00 TOTAL: \$303.75
<u>Work Requested:</u> Driver trip ticket from 5/7/18 1. Front end shakes at higher speeds. Road noise from driver's side tire. 2. A/C condensate leaking on to passenger floor. 3. Remove front plastic shield that is hanging down. Perform road test for front end shake at high speeds. There is some tire noise and pull. Inspect and locate choppy tires. Balance and rotate tires to mitigate shake and noise concern as much as possible. Re learn TPMS sensor positions. To completely eliminate the noise all tires will need to be replaced. The front end parts are all tight. Vehicle is safe to operate as is. Inspect for A/C condensate leaking on to the passenger side floor. Locate hole in bottom of HVAC case. Install cap/plug to seal HVAC case so that condensate will drain to the HVAC case drain. Refasten front air dam to front bumper. Mileage at time of service 62,567. Engine hours at time of service 5912. Engine idle hours at time of service 3184.						
P125400	85203 12 Ford F350 Pick-up 4WD 6.2L	05/07/2018	05/17/2018	CLO	1.00	Labor Cost: \$67.50 Mtl Cost: \$60.48 CONTRACT: \$0.00 TOTAL: \$127.98
<u>Work Requested:</u> A-SERVICE 8001040 & 7qts 7901006 (5w/20) Service inspect and advise as to vehicle condition Change engine oil and filter. Reset oil life monitor. Perform PM inspection. Miles at time of service 62,567. Engine hours at time of service 5912. Idle hours at time of service 3184.						
C109715	85203 12 Ford F350 Pick-up 4WD 6.2L	12/18/2017	02/11/2018	CLO	1.00	Labor Cost: \$52.00 Mtl Cost: \$63.84 CONTRACT: \$0.00 TOTAL: \$115.84
<u>Work Requested:</u> Brakes Right front brake overheating Check front brakes, machine front rotor. MILEAGE: 58024						
C109837	85203 12 Ford F350 Pick-up 4WD 6.2L	11/30/2017	12/07/2017	CLO	10.00	Labor Cost: \$520.00 Mtl Cost: \$1,177.75 CONTRACT: \$0.00 TOTAL: \$1,697.75
<u>Work Requested:</u> Drive-train Driver complained of noise in rear end. Drive not always engaging right away, sometimes slams into gear Test drove, was able to hear the noise, but transmission did not act up. Checked out noise on hoist, found both front wheel bearings bad and need brakes, replaced front wheel bearings and brakes on both axles, test drove, noise ok, tranny did not act up. MILEAGE: 57654						

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	C O S T S
P124442	85203 12 Ford F350 Pick-up 4WD 6.2L	08/21/2017	09/07/2017	CLO	1.00	Labor Cost: \$52.00 Mtl Cost: \$51.85 CONTRACT: \$0.00 TOTAL: \$103.85
<u>Work Requested:</u>						
A-SERVICE 8001040 & 7qts 7901006 (5w/20) Service inspect and advise as to vehicle condition						
Change oil and filter check over clean radaitor check brakes .1/4" left.top off fluids and tire air pressures and check lights.						
54887 mi.						
P123748	85203 12 Ford F350 Pick-up 4WD 6.2L	03/09/2017	04/14/2017	CLO	13.00	Labor Cost: \$676.00 Mtl Cost: \$827.64 CONTRACT: \$0.00 TOTAL: \$1,503.64
<u>Work Requested:</u>						
C-SERVICE ANNUAL/D-SERVICE (SEE OWNERS MANUAL)						
15,000 - INSPECT THE COOLANT CONCENTRATION AND ADDITIVE STRENGTH. ADD ENGINE COOLANT ADDITIVE IF NECESSARY. REPLACE FUEL FILTERS.						
45,000 - REPLACE AIR INLET FOAM FILTER (FA-1909).						
60,000 - CHANGE TRANSFER CASE FLUID. FLUSH AND REFILL ENGINE COOLANT. DO NOT ADD ENGINE COOLANT ADDITIVE.						
90,000 - INSPECT THE ACCESSORY DRIVE BELTS						
100,000 - CHANGE THE REAR AXLE FLUID. CHANGE CRANKCASE VENTILATION FILTER ASSY.						
150,000 - CHANGE TRANSMISSION FLUID AND FILTER. CHANGE FRONT AXLE FLUID. CHANGE TRANSFER CASE FLUID. REPLACE ACCESSORY DRIVE BELTS.						
Grease front axle u-joints, service transmission, with filter. Service transfer case change fluid, Top off front and rear differentials.						
Replaced and balanced all 4 tires, tires did not cooperate 100% thus took extra time. Replaced 8 upper spark plugs. replaced lower 8 spark plugs and wires 16 in all, air filter, clean MAF sensor, install tires on truck, reset tire monitor and test drive, stops and drives good.						
Notes: Coolant tested ok at this time, Front brake pads 45% left rear pads brakes 60% left. Let go at this time. Lots of body damage noted in history w.o. 4s before.						
49240[]						
P123568	85203 12 Ford F350 Pick-up 4WD 6.2L	01/04/2017	02/02/2017	CLO	1.50	Labor Cost: \$78.00 Mtl Cost: \$82.31 CONTRACT: \$0.00 TOTAL: \$160.31
<u>Work Requested:</u>						
A-SERVICE 8001040 & 7qts 7901006 (5w/20) Service inspect and advise as to vehicle condition						
85203 AH 12 Ford F-350 installed license plate lamp assemble tommy gate cover had to be removed for access. Done brought back to Arden hills garage. Cabin air not checked						
46748						
C108445	85203 12 Ford F350 Pick-up 4WD 6.2L	12/29/2016	12/29/2016	CLO	2.00	Labor Cost: \$100.00 Mtl Cost: \$0.00 CONTRACT: \$0.00 TOTAL: \$100.00
<u>Work Requested:</u>						
Driver complaint, slow leak in left rear tire						
REMOVE AND REPAIR SMALL HOLE IN LEFT REAR TIRE. REMOUNDED AND BALANCED TIRE - MILEAGE AT TIME OF SVC: 45697						
P122972	85203 12 Ford F350 Pick-up 4WD 6.2L	07/16/2016	08/04/2016	CLO	2.00	Labor Cost: \$100.00 Mtl Cost: \$52.37 CONTRACT: \$0.00 TOTAL: \$152.37
<u>Work Requested:</u>						
A-SERVICE 8001040 Service inspect and advise as to vehicle condition						
Changed engine oil and filter, replaced wiper blades, and performed a multi-point inspection, cleaned radiator, lubed doors						
40578						

Work Order Cost Summary

Work Order	Asset Number	Origination Date	Completion Date	Status	Actual Hours	COSTS
C107580	85203 12 Ford F350 Pick-up 4WD 6.2L	05/10/2016	05/10/2016	CLO	3.00	Labor Cost: \$150.00 Mtl Cost: \$0.51 CONTRACT: \$0.00 <hr/> TOTAL: \$150.51
<u>Work Requested:</u>						
Heating / Air Conditioning - A/C blows warm and pass side taillight is out §						
REPLACED RIGHT TAIL LAMP BULB, CHECKED A/C SYSTEM PRESSURES - SYSTEM LOW ON CHARGE - VISUAL INSPECTION SHOWED NO SIGNS OF LEAKS. EVACUATED AND VACUUM TESTED FOR LEAKS - TEST PASSED. RECHARGED SYSTEM AND TESTED - 42 DEG VENT TEMP. WASHED OUT CONDENSOR AND RADIATOR. MILEAGE: 37041						
P122430	85203 12 Ford F350 Pick-up 4WD 6.2L	02/12/2016	02/25/2016	CLO	2.00	Labor Cost: \$100.00 Mtl Cost: \$430.57 CONTRACT: \$0.00 <hr/> TOTAL: \$530.57
<u>Work Requested:</u>						
A-SERVICE 8001040 Service inspect and advise as to vehicle condition						
Changed oil and filter, replaced right front marker light, rotated tires, replaced air filter, replaced rightside mirror bezzel 34416						
C106851	85203 12 Ford F350 Pick-up 4WD 6.2L	09/23/2015	09/25/2015	CLO	4.50	Labor Cost: \$216.00 Mtl Cost: \$280.30 CONTRACT: \$0.00 <hr/> TOTAL: \$496.30
<u>Work Requested:</u>						
Drive-train - driver compliant front end noise §						
THE RIGHT FRONT WHEEL BEARING IS BAD. REPALCED RIGHT FRONT WHEEL HUB ASSEMBLY - MILEAGE: 31072						
P121558	85203 12 Ford F350 Pick-up 4WD 6.2L	06/05/2015	07/09/2015	CLO	5.00	Labor Cost: \$240.00 Mtl Cost: \$762.71 CONTRACT: \$0.00 <hr/> TOTAL: \$1,002.71
<u>Work Requested:</u>						
A-SERVICE 8001040 Service inspect and advise as to vehicle condition						
CHANGED OIL, INSPECTED BRAKES, CLEANED RADIATOR, LUBRICATED DOOR LOCKS AND HINGES, REPLACED 4 TIRES, TURNED REAR ROTORS AND REPLACED PADS - MILEAGE: 28948						
C106459	85203 12 Ford F350 Pick-up 4WD 6.2L	04/30/2015	05/05/2015	CLO	20.50	Labor Cost: \$984.00 Mtl Cost: \$1,290.74 CONTRACT: \$0.00 <hr/> TOTAL: \$2,274.74
<u>Work Requested:</u>						
Driver complaint: grinding noise						
Things found during inspection: Left front wheel U-joint has caps turning in yoke. Hubs both sides were in the auto position and not releasing. Inner stub shaft seal leak. Needs U-joint. Needs outboard yoke.						
Oil change due at 27,851 miles						
INSPECT FRONT 4 WHEEL DRIVE, NEED 2 LOCKED OUT HUBS 1 U-JOINT - LEFT FRONT AXLE, LEFT FRONT WHEEL BEARING ASSM. FRONT BRAKE PADS WITH ROTORS - MILEAGE: 26982						
P120870	85203 12 Ford F350 Pick-up 4WD 6.2L	10/22/2014	10/28/2014	CLO	1.00	Labor Cost: \$46.00 Mtl Cost: \$62.28 CONTRACT: \$0.00 <hr/> TOTAL: \$108.28
<u>Work Requested:</u>						
A-SERVICE Service inspect and advise as to vehicle condition						
LICENSE PLATE LAMP OUT - CLEAN OUT RADIATOR & CONDENSER - OIL CHANGE AS PER PM CHECKLIST - MILEAGE: 22851						

REPORT TOTALS	
ACTUAL HOURS:	102.00
LABOR:	\$6,007.50
MATERIAL:	\$7,313.73
CONTRACT:	\$0.00
GRAND TOTAL:	\$13,321.22